



Foundation Evaluation

Thursday, March 6, 2025

Good Morning,

On **Monday, March 3, 2025** we performed a visual assessment of the foundation of the residence located at **11302 Windermere Meadows in Austin, Texas 78759**. The purpose of this inspection was to determine if the foundation was performing its intended functions and if any remedial repairs was required.

During the inspection, elevations were taken using zip level PRO-2000 High Precision Altimeter. The elevations were recorded in a tenth of an inch where the engineering standard allows a deviation of one inch across a surface of thirty linear feet. All elevations were within tolerance and the foundation appears to be performing as intended. There is no need for foundation repair at this time.

- NO WORK NEEDED AT THIS TIME -

Sincerely,

A handwritten signature in black ink that reads "Wm. H. Bruecher, III". The signature is written in a cursive style.

Wm. H. Bruecher, III, President